

Q. - - -I have ordered 5mm polycord belting from the society, will this size provide an adequate drive for normal OT fly cutter work?

A. - - -5mm Polycord is fine for main drives (like headstock to flywheel or electric motor) but it is really too thick for driving a cutting frame. I use 3mm for most cutting frame belts but 4mm if I expect to do any heavy work or to drive a geared cutting frame, which takes more power. The smallest cutting frames may be driven by 2mm belt.